CERTIFICATE OF COMPLIANCE

Certificate Number EX28113

Report Reference EX28113-20200714

Issue Date 2020-JULY-14

Issued to: HOLZHAUER-PUMPEN GMBH

INDUSTRIESTRASSE 6-12 61184,, KARBEN, GERMANY

This certificate confirms that CENTRIFUGAL FIRE PUMPS, SPLIT CASE

representative samples of See Addendum page for Models/Product

Have been investigated by UL in accordance with the

Standard(s) indicated on this Certificate.

Standard(s) for Safety: UL 448 - Centrifugal Stationary Pumps for Fire-Protection

Service

Additional Information: See the UL Online Certifications Directory at

https://iq.ulprospector.com for additional information.

This *Certificate of Compliance* does not provide authorization to apply the UL Mark. Only the UL Follow-Up Services Procedure provides authorization to apply the UL Mark.

Only those products bearing the UL Mark should be considered as being UL Certified and covered under UL's Follow-Up Services.

Look for the UL Certification Mark on the product.



Bruce Mahrenholz, Director North American Certification Program

UL LLC





CERTIFICATE OF COMPLIANCE

Certificate Number
Report Reference

EX28113 EX28113-20200714

Issue Date 2020-JULY-14


This is to certify that representative samples of the product as specified on this certificate were tested according to the current UL requirements.,

Fire pumps, single stage

HS 80-350G, HS 100-320, HS 125-300, HS 125-380, HS 150-460, HS 200-350, HS 200-430, HS 250-490, HS 100-300, HS 150-310, HS 350-640, HS 25-250, HS 125-250S, HS 125-310, HS 200-500S, HS 125-400, HS 200-500, HS 250-640, HS 250-640, HS 250-500, HS 150-250, HS 150-420, HS 80-250, HS 150-330

Fire pumps, multistage

HS 150-450X2



Bruce Mahrenholz, Director North American Certification Program

UL LLC

Any information and documentation involving UL Mark services are provided on behalf of UL LLC (UL) or any authorized licensee of UL. For questions, please contact a local UL Customer Service Representative at http://ul.com/aboutul/locations/

